



California Regional Water Quality Control Board

San Diego Region



Alan C. Lloyd, Ph.D.
Secretary for
Environmental
Protection

Over 50 Years Serving San Diego, Orange, and Riverside Counties
Recipient of the 2004 Environmental Award for Outstanding Achievement from USEPA

Arnold Schwarzenegger
Governor

9174 Sky Park Court, Suite 100, San Diego, California 92123-4340
(858) 467-2952 • Fax (858) 571-6972
[http:// www.waterboards.ca.gov/sandiego](http://www.waterboards.ca.gov/sandiego)

July 21, 2005

In reply refer to:
SMC:50-4143.05:walsl

Mr. Richard Kennedy
Defense Energy Support Center
8725 John J. Kingman Road Ste. 294
Fort Belvoir, VA 22060-6222

Dear Mr. Kennedy:

**SUBJECT: DRAFT SITE ASSESSMENT REPORT - TANK 45 DEFENSE FUEL
SUPPORT POINT (DFSP) POINT LOMA (SPO600-03-D-5315)
FLEET INDUSTRIAL SUPPLY CENTER (FISC) FUEL FARM**

The Draft Site Assessment Report, received by the Regional Board on July 4, 2005, adequately describes the impacts to soil and ground water from releases of petroleum hydrocarbons at Tank 45. It is our understanding that the Navy recommends extending the free product recovery system developed for Tank 43 north to include existing Tank 45 monitoring wells as well as installing additional wells to further define the current estimated toe of the plume. We concur with your recommendations but have the following comment.

Our review of the subject document included review of the State Board Geotracker website. The Geotracker case file for FISC Tank 45 does not contain any electronic laboratory data. Submittal of electronic soil and ground water data became a requirement under State Board regulations adopted in September 2001. The regulations were expanded in January 2005 to include electronic submittal of all reports not only laboratory data and well location. Additionally, the Regional Board notified the Navy of this requirement via our letter dated December 23, 2003. The Navy must submit electronic copies of all reports and laboratory data to Geotracker. All electronic reporting to Geotracker must be complete before the Regional Board will proceed to no further action at this site. Please keep this comment in mind for all tank cases within the fuel farm.

Please contact me if you have any questions at (858) 467-2970 or Lwalsh@waterboards.ca.gov. The heading portion of this letter includes a Regional Board code number noted after "In reply refer to:" In order to assist us in the processing of your correspondence please include this code number in the heading or subject line portion of all correspondence and reports to the Regional Board pertaining to this matter.

California Environmental Protection Agency

Mr. Kennedy
FISC Tank 45
Draft Site Assessment Report

- 2 -

July 21, 2005

Respectfully,

LAURIE A. WALSH
Water Resource Control Engineer
Site Mitigation and Cleanup Unit

LAW:jpa:law:tank 45 rsp to Dft SA Rpt.doc

Cc: Mr. Chris Corey P.G., Shaw Environmental, 1230 Columbia Street, Suite 1200 San Diego,
CA 92101

Mr. Steve Frey, Fleet and Industrial Supply Center, Fuel Terminal, 199 Rosecrans St. Bldg.
50, San Diego, CA 92106-5000

Mr. Jeremiah Glover, Navy Region Southwest, Naval Base Point Loma, Attn:
Environmental Office 2nd Floor, Bldg 140, 140 Sylvester Road, San Diego, CA 92106-5321

Mr. Jason Strum, Southwest Naval Facilities Engineering Command, 2585 Callagan Hwy
Bldg 99 (Code OPME.JS) San Diego, CA 92136

Mr. Alan Vancil, Southwest Naval Facilities Engineering Command, 2585 Callagan Hwy
Bldg 99 (Code OPME.AV) San Diego, CA 92136

California Environmental Protection Agency

Recycled Paper
